Rockwell Automation

1 Allen-Bradley Drive
Mayfield Heights, OH 44124-6118 USA
Telephone 440-646-4051
FAX: 440-646-4045

Subject: US Export Classification Information for Stratix 8000 Hardware (HW) and Firmware (FW)

This letter is provided by Rockwell Automation to inform the requester of the Export Control Classification Number (ECCN) for the following Rockwell Automation products

| **Rockwell Automation Catalog No.** | **ECCN** | **HTS number** |
|---|---|---|
| Stratix 8000 Firmware (FW)<br>(FW File: IES lanbasek9-tar.152-3.EA1.fc2.tar) | 5D002 | N/A |
| 1783-MCS Stratix 8000 (HW) | 5A992 | 8517.62.0050 |

Please also not that the Exporter of Record will need to review the final product to be exported to determine the ECCN and is responsible for complying with the U.S. Export Administration Regulations. In addition, an ECCN does not solely determine or remove the need for an export license under the Export Administration Regulations (EAR). It is also based on the end use(r). In the event a U.S. Agent is acting as an Export of Record for the product identified herein, it is their responsibility to comply with the U.S. Export Administration Regulations

Please note that the information released herein does not apply to any future shipment of the identical products.

If there are any questions, please let us know.

Sincerely,

Ronald P. Ricca
FTA Project Manager
Rockwell Automation